




LIGHT BOOM | COMPACT METRICAL



PARTS INCLUDED

Main Assembly
Head Extension
Head Stud
Handle
Cord Clips (2)
Cable straps (2)
Weight Bag

ASSEMBLY INSTRUCTIONS

1. Slide Head Extension onto Mount Block.
2. Install Handle into bottom hole of Head Extension.
3. Attach Weight Bag onto Glide and secure using the two Thumb Screws provided.

SET UP INSTRUCTIONS

1. Use heavy-duty stand with 5/8"x2"+stud. A 1 1/8"+to 5/8"+adapter may be needed for use on Cine stands. Set most of the light boom onto stand.
2. Mount Light Head onto Head Stud.
3. Use Cord Clips or Cable Straps to attach Power Cable to Main Beam or Cross Beam.
4. Loosen Weight Bag Thumb Screws and reposition bag in Track to counter-balance weight of Lights.

WEIGHT BAG FILL INSTRUCTION

1. Pull open the closure tabs at the bottom of weight bag.
2. Insert a funnel into slotted opening.
3. Pour in lead shot to desired level. Pour in an equal amount into the other side of the bag.

Note: Lead shot is recommended for fill, but steel shot could also be used. Do not use sand, as it will not provide enough weight.

For Red Wing Standard (Full-size): 2 bags

* Fill each side to about 2.8 kg (5.6 kg/bag) ≈6.25 lbs (12.5 lbs/bag)

For Red Wing Compact: 1 bags

* Fill each side to about 3.4 kg (6.8 kg/bag) ≈7.5 lbs (15 lbs/bag)

4. After filling, press closure tab down tightly.